

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

II General information

1. Report Time Period: From (mo./yr.) Jan, 1993 To (mo./yr.) Jan 1994
2. DOGM File Number (Mine No): S/019/033
3. Mine Name: Petrified Tree #8
4. Mineral(s) Mined (or permitted to mine): Uranium and Vanadium

5. Type of mine ☐ Surface Mine or ☒ Underground Mine

6. Legal Description (Location of Lands Affected):

1/4, 1/4, Section 27, Township 24S, Range 25E

1/4, 1/4, Section, Township, Range

1/4, 1/4, Section, Township, Range

7. Name of Operator or Company: Umetco Minerals Corporation

8. Permanent Street Address: 2754 Compass Drive, Suite 280

City, State, Zip: Grand Junction, Co. 81506

Phone: 303-245-3700

9. Company Representative (or designated operator):

Name: Robert F Barnett

Title: Coordinator of Environmental & Regulatory Affairs

Business Address: P O Box 506

City, State, Zip: Dove Creek, Co. 81324

Phone: 303-677-2711

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☐ No ☒
2. If active, how much ore or mineral was mined?

3. How much **additional acreage** was disturbed during the past year? None

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

5. How much acreage was **reclaimed** during the past year? All was reclaimed

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. The portal was bulk headed off 30 feet back in mine and filled with waste from there out to the surface. The waste dump was contoured into the surrounding areas. The use of berms, scarification, fertilization, and revegetation to mitigate the surface erosion and prevent sediments from leaving the reclaimed site.

7. What is the **total disturbed acreage** at years end? 0.5

8. Briefly summarize any mining and/or reclamation plans for the upcoming year. Reseed if necessary

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): R. A. Van Horn

Title of Operator: Director of Operations

Signature of Operator: 

Date: January 10, 1994